Viva Energy Australia Pty Ltd

Clyde Terminal Complaints Register

| Date | Origin of Complaint | Project Area | Incident | Description | Response |
|--|------------------------|--------------------|--|---|--|
| 30-Jun-2015 | Neighbour | Demolition Area 18 | Cutting Fin Fan pyrophoric residue which gave off unpleasant odour | Cutting Fin Fan pyrophoric residue which gave off unpleasant odour | Works stopped. Works cart moved to deluge cutting with water while works were completed. |
| No complaints in 2016 | - | - | - | - | - |
| No complaints in 2017 | - | - | - | - | - |
| No complaints in 2018 | - | - | - | - | - |
| No complaints in 2019 | - | - | - | - | - |
| No complaints in 2020 | - | - | - | - | - |
| No complaints in 2021 | - | - | - | - | - |
| No complaints in 2022 | - | - | - | - | - |
| No complaints in 2023 | - | - | - | - | - |
| No complaints in 2024 (to 20 th September) | - | - | - | - | - |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |

Last updated: 20 September 2024